COPY / OF I

I-28-200532- 8

Copy 8 of 9 copies

2 April 1968

This document contains

4 pages.

#### EVALUATION SUMMARY

Mission C-058C

1. Processing and Titling - Good/Field

2. Physical Condition - Good

3. Hypo Retention Negligible

4. Exposure (based on density) - Medium

5. General Comments:

- A. Drying marks on emulsion on all parts of 9L and 9R.
- B. Emulsion rub on all parts head to tail of 9L and 9R.
- C. Intermittent title transfer noted on all parts of 9L and 9R.
- D. A few kinks, pinholes and embedded dirt on all parts of 9L and 9R.

#### MISSION NO. C-058C EVALUATION REPORT

Evaluated By	ୟ.୯.		Camera	9L/9R/Tracker
Evaluation Date	21 March 196	58	Emulsion	3401/3401/3404
Frank Water		<b>~</b> -		
Film Metering		Good		
Film Tracking		Good		
Vacuum Failure		<b>No</b> ne		
Clock Operation Expo	sure	Good		
Counter Operation		Operational	-	
Data Chamber (image	quality)	Good.		
Apparent Resolution		Normal		
Apparent Granularity	,	Normal		•
Density		Medium		
Contrast		Medium		

### Discrepancies: 9L

<u>Part</u>	<u>Frames</u>	Comments
1	1-10 80-81 103-104 132-133	Intermittent base scratch Splice
2	134-266 236-237	Emulsion scratches Splice
3	267-399 343-344 369-370	Intermittent emulsion scratch Splice
4	502 <b>-</b> 503	Splice
5	628 635 <b>-</b> 636 664	Emulsion dig Splice Lacquer in format
6	742-743	Splice
7	901-902 902	Splice Emulsion dig

Page 2

## Discrepancies (Cont'd) 9L Camera

<u>Part</u>	Frames	Comments
8	932 1034-1035	Moisture spot Splice
9	1160-1161	Splice
10	1198-1200 1300-1301	Base scratches Splice
11	1433-1444	Splice
12	1566-1568	Splices
13	1699-1700	Splice
14	1782 1832 <b>-183</b> 3	Base scratches Splice
15	1933,1965-1966	Splice
9R Camer	<u>a</u>	
1	1-33 1-84 103-104 122-123 132-133	Intermittent static titled edge Base scratch Splice
2	134-266 236-237 257	Intermittent static titled edge Splice Lacquer smear
3	368 369-370 392-393 399	Emulsion scratch Splice ** Emulsion pickoff
4	503 502 <b>-</b> 503	Emulsion pickoff Splice
5	595,631 600 635-636	Emulsion pickoff Lacquer smear Splice
6	768 <b>-</b> 769 787 <b>-</b> 788	Splice
7	867-868,914-915 921-923 799-931 901-902 905	Moisture spot  Intermittent emulsion scratch Splice Ferrotyping spot

Page 3

# Discrepancies (Cont'd) 9R Camera

Part	Frames	Comments
8	952,963,967-968 1034-1035	Moisture spot Splice
9	1136-1140	Moisture spot
10	1212,1232,1235, 1293,1312,1313, 1324,1325 1300-1301	Moisture spot Splice
11	1331 1372 1396 1433-1434 1331-1463	Crease Emulsion scratch Ferrotyping Splice Intermittent moisture spot
12	1469,1494,1505, 1556,1578,1579 1566,1567	Moisture spot Splice
13	1608-1609, 1699-1700 1642 1702	Splice Emulsion pickoff Lacquer smear
14	1730-1862 1740 1744,1832-1833 1833	Intermittent static on titled edge Lacquer smear Splice Emulsion digs
15	1865,1868,1902, 1971,1981	Moisture spot
Tracker	Record (35mm film	type 3404)
	1	Kink
	1-383	Intermittent dirt, intermittent base and emulsion scratches
	158	Pinholes

Page 4